



Tempasure™

Product Information

Product Description: Temperature Assurance Indicator

Standard Range: -20 to +10°C

Size: 54mm x 17.5mm

Accuracy: +/-2°C

Directions: Allow sensor to stabilise at product temperature. Pull safety tab to activate sensor. Remove release liner and attach with self adhesive backing.

Indication: A clear window indicates that the unit has not been exposed to critical low temperatures. Indicator window shows red when exposed to low temperature that is at or below its rating.

Storage: Store in dry, cool conditions

24/10/2008

Riverside Buildings, Dock Road, Connah's Quay, Flintshire, CH5 4DS