

Thermax[®]

Instructions for Use

Product Description: Irreversible Temperature Labels

Standard Range: 29-290°C / 84-554°F

Directions: Peel indicator from release paper

Apply to a clean, grease free surface ensuring that the indicator has adhered to the surface

A colour change from silver white / orange to black indicates that the rating has been reached.

Storage: Store in a cool dry place below 18°C (64°F)