
Advanced Thermographic Technologies

Colotemp[®] Color Change Crayons

Instructions for Use

Mark preheated surface where the measurement is desired

Immediate colour change indicates that the measurement surface is higher than the crayon rating

A colour change after (2) two seconds indicates that the measurement surface is lower than the crayon rating

Accuracy $\pm 5^{\circ}$ C